



Adrienchina

REPORTE INSPECCIÓN PRE-EMBARQUE


Evaluación detallada de calidad,
cantidad y cumplimiento antes del
envío de la mercancía




adrienchina



adrienchina11

| | | | |
|---|------------------------|-------------|--------------|
|  Adrienchina | Client: | | Page 1 of 48 |
| | Report Date: | Feb.5th2026 | |
| | Inspection No.: | PSI-2602091 | |
| INSPECCION PRE-EMBARQUE | Form No.: | T-RF-001 V1 | |


I、GENERAL INFORMATION

| | | | | |
|-----------------------------------|------------------------------|--|------------------------------|--|
| Client: | |  | | |
| Product description: | Tubular type UHT sterilizer | | | |
| P /O No.: | - | | | |
| Order quantity: | 1 set | | | |
| Supplier: | - | | | |
| Inspection date: | Feb.5th 2026 | | | |
| Inspection location: | Wenzhou, Zhejiang, China | | | |
| Service type: | Pre-shipment Inspection | | | |
| Inspector: | Mark | | | |
| Further reference information: | | | | |
| <input type="checkbox"/> Pictures | <input type="checkbox"/> P/O | <input type="checkbox"/> SPEC | <input type="checkbox"/> P/I | <input checked="" type="checkbox"/> Others |

II、REMARKS

| | |
|------------------|---|
| General Remarks: | |
| 1 | At time of our attendance, 1 set of tubular type UHT sterilizer was found stored in supplier's warehouse. |
| 2 | The device was running well, no abnormality was found during performance test. |
| 3 | The visual quality was found in basically normal condition. |
| 4 | Most of the instruction manuals and certificates are in Chinese. |
| 5 | The warning labels on some components are in Chinese. |




| | | | |
|--|------------------------|-------------|--------------|
|  Adrien China | Client: | | Page 2 of 48 |
| | Report Date: | Feb.5th2026 | |
| INSPECCION PRE-EMBARQUE | Inspection No.: | PSI-2602091 | |
| | Form No.: | T-RF-001 V1 | |



6 For 200kg per hour steam generator and Watersoftener system, the switch indicators on the control box are in Chinese.



| | | | |
|---|------------------------|-------------|--------------|
|  Adrienchina | Client: | | Page 3 of 48 |
| | Report Date: | Feb.5th2026 | |
| | Inspection No.: | PSI-2602091 | |
| INSPECCION PRE-EMBARQUE | Form No.: | T-RF-001 V1 | |

III、 SPECIFICATION

| Spec. on PI | Actual founding |
|--------------------------------|----------------------------------|
| Machine frame | Passed |
| PLC | Siemens |
| Touchscreen | MCGS (Spanish, English, Chinese) |
| Gasifier | Zhongbang |
| Motors | LICHAO |
| Gas burner | Huaxin |
| Cooling water tower | Lingfeng |
| Safety valve and warning light | Passed |
| Centrifugal pump | Chengxu |
| Voltage | 220V/60Hz/3Phase |

IV、 ON-SITE TESTS

| NO. | Description | Inspection level | Sample size | Result/Reading |
|-----|----------------------------|------------------|-------------|----------------|
| 1、 | Basic function test | - | 1 set | Passed |
| 2、 | Emergency stop button test | - | 1 set | Passed |

Result: **PASSED** **PENDING** **FAILED**

V、 PHOTOS

0.5T per hour full-auto steam heating tubular type UHT sterilizer





Adrienchina

Client:

Report Date:

Feb.5th2026

Inspection No.:

PSI-2602091

Page 4 of 48

INSPECCION PRE-EMBARQUE

Form No.:

T-RF-001 V1





Adrienchina

INSPECCION PRE-EMBARQUE

Client:

Report Date:

Feb.5th2026

Inspection No.:

PSI-2602091

Page 5 of 48

Form No.:

T-RF-001 V1





Adrienchina

INSPECCION PRE-EMBARQUE

Client:

Report Date:

Feb.5th2026

Inspection No.:

PSI-2602091

Page 6 of 48

Form No.:

T-RF-001 V1





Adrienchina

INSPECCION PRE-EMBARQUE

Client:

Report Date:

Feb.5th2026

Inspection No.:

PSI-2602091

Page 7 of 48

Form No.:

T-RF-001 V1





Adrienchina

INSPECCION PRE-EMBARQUE

Client:

Report Date:

Feb.5th2026


Inspection No.:

PSI-2602091

Page 8 of 48

Form No.:

T-RF-001 V1





Adrienchina

INSPECCION PRE-EMBARQUE

Client:

Report Date:

Feb.5th2026


Inspection No.:


PSI-2602091





Page 9 of 48


Form No.:


T-RF-001 V1



| | | | |
|---|------------------------|-------------|---------------|
|  Adrienchina | Client: | | Page 10 of 48 |
| | Report Date: | Feb.5th2026 | |
| INSPECCION PRE-EMBARQUE | Inspection No.: | PSI-2602091 | |
| | Form No.: | T-RF-001 V1 | |



| | | | |
|---|---------------------|-------------|---------------|
|  <p>Adrienchina</p> | Client: | | Page 11 of 48 |
| | Report Date: | Feb.5th2026 | |
| Inspection No.: | PSI-2602091 | | |
| INSPECCION PRE-EMBARQUE | Form No.: | T-RF-001 V1 | |





Adrienchina

INSPECCION PRE-EMBARQUE

Client:

Report Date:

Feb.5th2026






Inspection No.:

PSI-2602091

Page 12 of 48

Form No.:

T-RF-001 V1





Adrienchina

INSPECCION PRE-EMBARQUE

Client:

Report Date:

Feb.5th2026



Inspection No.:

PSI-2602091

Page 13 of 48

Form No.:

T-RF-001 V1





Adrienchina

INSPECCION PRE-EMBARQUE

Client:

Report Date:

Feb.5th2026

Inspection No.:


PSI-2602091

Page 14 of 48


Form No.:

T-RF-001 V1



| | | | |
|---|---------------------|-------------|---------------|
|  Adrienchina | Client: | | Page 15 of 48 |
| | Report Date: | Feb.5th2026 | |
| Inspection No.: | PSI-2602091 | | |
| INSPECCION PRE-EMBARQUE | Form No.: | T-RF-001 V1 | |



| | | | |
|---|---------------------|-------------|---------------|
|  Adrienchina | Client: | | Page 16 of 48 |
| | Report Date: | Feb.5th2026 | |
| Inspection No.: | PSI-2602091 | | |
| INSPECCION PRE-EMBARQUE | Form No.: | T-RF-001 V1 | |





Adrienchina

INSPECCION PRE-EMBARQUE

Client:

Report Date:

Feb.5th2026

Inspection No.:

PSI-2602091

Page 17 of 48

Form No.:

T-RF-001 V1





Adrienchina

INSPECCION PRE-EMBARQUE

Client:

Report Date:

Feb.5th2026

Inspection No.:

PSI-2602091

Page 18 of 48

Form No.:

T-RF-001 V1





Adrienchina

INSPECCION PRE-EMBARQUE

Client:

Report Date:

Feb.5th2026

Inspection No.:

PSI-2602091

Page 19 of 48

Form No.:

T-RF-001 V1





Adrienchina

INSPECCION PRE-EMBARQUE

Client:

Report Date:

Feb.5th2026


Inspection No.:

PSI-2602091

Page 20 of 48

Form No.:

T-RF-001 V1





Adrienchina

INSPECCION PRE-EMBARQUE

Client:

Report Date:

Feb.5th2026

Inspection No.:

PSI-2602091

Page 21 of 48

Form No.:

T-RF-001 V1





Adrienchina

INSPECCION PRE-EMBARQUE

Client:

Report Date:

Feb.5th2026

Inspection No.:

PSI-2602091

Page 22 of 48

Form No.:

T-RF-001 V1





Adrienchina

INSPECCION PRE-EMBARQUE

Client:

Report Date:

Feb.5th2026

Inspection No.:

PSI-2602091

Page 23 of 48

Form No.:

T-RF-001 V1





Adrienchina

INSPECCION PRE-EMBARQUE

Client:

Report Date:

Feb.5th2026

Inspection No.:

PSI-2602091

Page 24 of 48

Form No.:

T-RF-001 V1





Adrienchina

INSPECCION PRE-EMBARQUE

Client:

Report Date:

Feb.5th2026

Inspection No.:

PSI-2602091

Page 25 of 48

Form No.:

T-RF-001 V1





Adrienchina

INSPECCION PRE-EMBARQUE

Client:

Report Date:

Feb.5th2026

Inspection No.:

PSI-2602091

Page 26 of 48

Form No.:

T-RF-001 V1





Adrienchina

INSPECCION PRE-EMBARQUE

Client:

Report Date:

Feb.5th2026

Inspection No.:


PSI-2602091

Page 27 of 48

Form No.:

T-RF-001 V1



| | | | |
|---|---------------------|-------------|---------------|
|  Adrienchina | Client: | | Page 28 of 48 |
| | Report Date: | Feb.5th2026 | |
| Inspection No.: | PSI-2602091 | | |
| Form No.: | T-RF-001 V1 | | |
| INSPECCION PRE-EMBARQUE | | | |



200kg per hour steam generator





Adrienchina

INSPECCION PRE-EMBARQUE

Client:

Report Date:

Feb.5th2026

Inspection No.:


PSI-2602091

Page 29 of 48

Form No.:

T-RF-001 V1



| | | | |
|---|---------------------|-------------|---------------|
|  Adrienchina | Client: | | Page 30 of 48 |
| | Report Date: | Feb.5th2026 | |
| Inspection No.: | PSI-2602091 | | |
| INSPECCION PRE-EMBARQUE | Form No.: | T-RF-001 V1 | |





Adrienchina

INSPECCION PRE-EMBARQUE

Client:

Report Date:

Feb.5th2026


Inspection No.:

PSI-2602091

Page 31 of 48

Form No.:

T-RF-001 V1





Adrienchina

INSPECCION PRE-EMBARQUE

Client:

Report Date:

Feb.5th2026


Inspection No.:


PSI-2602091





Form No.:

T-RF-001 V1

Page 32 of 48



| | | | |
|--|---------------------|-------------|---------------|
|  Adrien China | Client: | | Page 33 of 48 |
| | Report Date: | Feb.5th2026 | |
| Inspection No.: | PSI-2602091 | | |
| Form No.: | T-RF-001 V1 | | |
| INSPECCION PRE-EMBARQUE | | | |





Adrienchina

INSPECCION PRE-EMBARQUE

Client:

Report Date:

Feb.5th2026


Inspection No.:

PSI-2602091

Page 34 of 48


Form No.:

T-RF-001 V1




Water softener system



| | | | |
|---|---------------------|-------------|---------------|
|  Adrienchina | Client: | | Page 35 of 48 |
| | Report Date: | Feb.5th2026 | |
| Inspection No.: | PSI-2602091 | | |
| INSPECCION PRE-EMBARQUE | Form No.: | T-RF-001 V1 | |



| | | | |
|---|------------------------|-------------|---------------|
|  <p>Adrienchina</p> | Client: | | Page 36 of 48 |
| | Report Date: | Feb.5th2026 | |
| INSPECCION PRE-EMBARQUE | Inspection No.: | PSI-2602091 | |
| | Form No.: | T-RF-001 V1 | |





Adrienchina

INSPECCION PRE-EMBARQUE

Client:

Report Date:

Feb.5th2026

Inspection No.:

PSI-2602091

Page 37 of 48


Form No.:

T-RF-001 V1



10T cooling water tower



| | | | |
|---|---------------------|-------------|---------------|
|  Adrienchina | Client: | | Page 38 of 48 |
| | Report Date: | Feb.5th2026 | |
| Inspection No.: | PSI-2602091 | | |
| INSPECCION PRE-EMBARQUE | Form No.: | T-RF-001 V1 | |





Adrienchina

INSPECCION PRE-EMBARQUE

Client:

Report Date:

Feb.5th2026

Inspection No.:


PSI-2602091

Page 39 of 48

Form No.:

T-RF-001 V1






| | | | |
|---|---------------------|-------------|---------------|
|  Adrienchina | Client: | | Page 40 of 48 |
| | Report Date: | Feb.5th2026 | |
| Inspection No.: | PSI-2602091 | | |
| Form No.: | T-RF-001 V1 | | |
| INSPECCION PRE-EMBARQUE | | | |



Spare parts



| | | | |
|--|---------------------|-------------|---------------|
|  Adrien China | Client: | | Page 41 of 48 |
| | Report Date: | Feb.5th2026 | |
| Inspection No.: | PSI-2602091 | | |
| Form No.: | T-RF-001 V1 | | |
| INSPECCION PRE-EMBARQUE | | | |





Adrienchina

INSPECCION PRE-EMBARQUE

Client:

Report Date:

Feb.5th2026

Inspection No.:

PSI-2602091

Page 42 of 48

Form No.:

T-RF-001 V1





Adrienchina

INSPECCION PRE-EMBARQUE

Client:

Report Date:

Feb.5th2026

Inspection No.:

PSI-2602091

Page 43 of 48

Form No.:

T-RF-001 V1





Adrienchina

INSPECCION PRE-EMBARQUE

Client:

Report Date:

Feb.5th2026

Inspection No.:

PSI-2602091

Page 44 of 48


Form No.:

T-RF-001 V1



Product size



| | | | |
|---|---------------------|-------------|---------------|
|  Adrienchina | Client: | | Page 45 of 48 |
| | Report Date: | Feb.5th2026 | |
| Inspection No.: | PSI-2602091 | | |
| INSPECCION PRE-EMBARQUE | Form No.: | T-RF-001 V1 | |





Adrienchina

INSPECCION PRE-EMBARQUE

Client:

Report Date:

Feb.5th2026

Inspection No.:

PSI-2602091

Page 46 of 48

Form No.:

T-RF-001 V1





Adrienchina

INSPECCION PRE-EMBARQUE

Client:

Report Date:

Feb.5th2026

Inspection No.:


PSI-2602091

Page 47 of 48

Form No.:

T-RF-001 V1



| | | | |
|---|---------------------|-------------|---------------|
|  Adrienchina | Client: | | Page 48 of 48 |
| | Report Date: | Feb.5th2026 | |
| Inspection No.: | PSI-2602091 | | |
| INSPECCION PRE-EMBARQUE | Form No.: | T-RF-001 V1 | |



*****This is The End of the Report *****